GENERAL MIXING INSTRUCTIONS - 12" HOLE & DOWN

	Per 500 Gal
RheoXanD	For use with or without bentonite. Add 0.5 – 2 jugs until viscosity reaches desired level.
RheoPac	For use with or without bentonite. Add 0.5 – 2 jugs as needed for fluid loss control.
LiftGuardDRY	Prehydrate bentonite in water. Add 0.5 – 2 jugs for maximum hole cleaning and cuttings transport.
HydropH ⁺	Prior to making bentonite additions to the water, add $0.5-2$ jugs directly into the fluid or through the mixing hopper. Then add bentonite.

Available in $\frac{1}{2}$ gallon jugs and 5 gallon buckets.

